



Photo 1. View south of the intersection of Rattlesnake Road and Line 1228. Phase 1 Restoration Area is in the background.



Photo 3. View of pickleweed patch along eastern terminus of Rattlesnake Road. This isolated patch of pickleweed would be indirectly impacted due to construction of the restoration berm.




Photo 2. View east along Rattlesnake Road. Line 1228 will be located between the Aera Energy pipe rack and the roadway.



Photo 4. View south along Road 70 near the Rattlesnake Road intersection.

Site Photos (Sheet 1 of 3)

Figure 5a